

HOW TO MEASURE YOUR POST DRILLING

- A.) TAKE 1ST MEASUREMENT FROM THE TOP OF POST (NOT TOP OF CAP), TO THE CENTER OF THE 1ST HOLE
- B.) TAKE YOUR 2ND MEASUREMENT FROM THE CENTER OF THE 1ST HOLE TO THE CENTER OF THE 2ND HOLE
- C.) TAKE YOUR 3RD MEASUREMENT FROM THE CENTER OF THE 2ND HOLE TO THE CENTER OF THE 3RD HOLE
- D.) MEASURE THE WIDTH OF YOUR POST SO IT CAN BE SIZED ACCORDINGLY FOR YOUR REPLACEMENT POST

